

Appendix C – Site Photos



**Darebin Creek near Metropolitan Ring Road
Off Ramp to Metropolitan Ring Road**



**Carol Crescent, Mill Park near transmission line
Showing high shrink/swell potential of basaltic clays**



**McDonalds Rd west of alignment
Showing slightly weathered basalt near surface adjacent to Henderson Rd Drain**



**Corner Bindts Rd & Harvest Home Rd
Showing basalt cobbles and boulders at surface**



Bindts Road
Showing basalt tors at surface



Bindts Road
Showing stone fence along west side of Bindts Rd



**Epping Road west side near Bridge Inn Rd
Showing stony rise, basalt**