

Appendix C – Site Photos



Native Grasslands Reserve at Werribee Tip



Gantry over railway at Bulban Rd



**Ball Rd looking northeast
Showing basalt plains**



**Greens Rd looking northeast
Showing basalt plains**



Dam at Ballan Rd



**Werribee River
Showing deep river cutting**



Dam on Middle Road – showing non-rippable basalt in dam bank



Dam on Troups Road – showing large basalt boulders close to surface



Beattys Rd – showing spiny rush adjacent to Kororoit Creek, indicating potential presence of salt-affected soils



**Kororoit Ck on Sinclairs Rd
Showing deep creek cutting**



Erosion on Sinclairs Rd north of Kororoit Ck



Morefield Ct
Showing deeply intersected terrain



Culvert on Morefield Ct



**Morefiled Ct creek bed adjacent to culvert
Showing potentially high water flow at times**



Dam on Bulla-Diggers Rest Rd



**Holden Bridge across Jacksons Ck on Bulla-Diggers Rest Rd
Showing deep creek cutting**



**Bulla-Diggers Rest Rd, looking west
Showing deep cuts**



**Back of Bulla tip and quarry, looking southeast from Batey Ct
Showing deeply intersected terrain**



Back of Bulla tip and quarry (detail), looking southeast from Batey Ct



**Former Boral Bulla Quarry on Sunbury Rd, looking south
Showing deep excavation**



Detail of Former Boral Bulla Quarry on Sunbury Rd



Lighthouse Gully on Wildwood Rd (Bulla), looking west



Basalt surface rock stockpiles next to Mickleham Rd



Black basaltic clay next Hume FWY near Donovans Lne